


12 EASY STEPS TO SAFE ISOLATION



Process for re-energising the circuit/system

- Step 1:** After completing the work inspect and test in accordance with Part 6 BS 7671 (dead tests).
- Step 2:** Cancel permits (if issued), remove locking off devices, locks and labels and restore electrical supply.
- Step 3:** Complete testing (live tests). Commission circuit equipment.
- Step 4:** Complete and issue appropriate test certificates / reports.

Graphic reproduced in conjunction with the Electrical Safety Roundtable (ESR).