

## IR 1200 - Electrician specific infrared thermometer

Infrared thermometers take an average reading across a circular area the IR1200's two dot laser guidance clearly defines this area so you know exactly what you are measuring.

## Look at these other great features

- Measures up to I200°C
- Second channel for contact temperature measurement for use with K type connectors (thermocouple included)
- Independent ambient temperature measurement
- Easy adjustments for emissivity
- Data hold
- Ave, Min & Max function



## **OPTIONAL ACCESSORIES**

